



**Sieve Analysis Report**

<b>CLIENT:</b>	Metro Green 100A Oak Street Mt. Vernon, NY 10550	<b>DATE:</b>	February 2, 2019
<b>PROJECT:</b>	100A Oak Street Mt. Vernon, NY 10550	<b>LAB NO:</b>	16257
<b>SAMPLE ID:</b>	Clean fill	<b>TIME IN:</b>	9:00AM
<b>RECEIVED:</b>	1/25/19	<b>TIME OUT:</b>	10:00AM
<b>INSPECTOR:</b>	J. Aviles		

RESULTS	
Sieve Size	% Passing
¾"	100
½"	95.1
3/8"	93.0
#4	89.4
#8	80.0
#16	65.9
#30	48.2
#50	27.4
#100	13.3
#200	6.25

<b>EQUIPMENT USED:</b>	Sieves; SN #002 Shaker; SN 001
------------------------	-----------------------------------

Brown silt with little sand and gravel

Respectfully submitted,  
CERTIFIED TESTING LABORATORIES, INC.

RZ/dk

*[Signature]*  
Richard J. Zaloum, PE



CTL S0FS-3  
6/1/12

CERTIFIED TESTING LABORATORIES, INC.

CLIENT: METRO GREEN

# GRAIN SIZE DISTRIBUTION

U. S. STANDARD SIEVE SIZE

